

## Portable USB Thermometer HT-161

### Specifications:

Record 21000 temperature and humidity counts simultaneously.

LCD display for easily reading

USB connect to PC

Temp measurement range  $-40^{\circ}\text{C}\sim 105^{\circ}\text{C}$   $-40^{\circ}\text{F}\sim 221^{\circ}\text{F}$

Temp measurement accuracy  $\pm 1^{\circ}\text{C}$   $\pm 2^{\circ}\text{F}$

Temp display resolution  $0.1^{\circ}\text{C}$   $0.1^{\circ}\text{F}$

Humidity measurement range  $0\% \text{RH}\sim 100\% \text{RH}$

Humidity measurement accuracy  $\pm 3\% \text{RH}$

Humidity display resolution  $0.1\% \text{RH}$