## TBT-08H Digital Food Thermometer, Meat thermometer

Details for China Manufacture Meat Thermometer For Kitchen (Fast Reading)

Profession, Stability and High accuracy

Easily Switch degrees Fahrenheit and Celsius function

Convinent to be used

Auto power off

4 bottons with LCD display

Meat thermometer is easy to measure food temperature, which is safe to test the temperature. Please read the instruction before using this item.

## Instruction

- 1.ON/OFF key: Awitching
- 2.C/F Key: the display mode, this button can be C/F Conversion function
- 3.Hold key :Please press the bottom HOLD when it is under normal working state, then the temperature will be held, and press it once more it will back to normal working state.
- 4.MIN/MAX key: To show you the Min/Max temperature it used to measure.

## **Specification**

- 1. Measuring range:-50C to 300C
- $2. Accuracy: \pm 0.1 \, ^{\circ}\text{C}, -20 \sim 100 \, ^{\circ}\text{C}(-4 \sim 212 \, ^{\circ}\text{F}): \pm 1 \, ^{\circ}\text{C}, 100 \sim 200 \, ^{\circ}\text{C}(212 \sim 392 \, ^{\circ}\text{F}): \pm 2 \, ^{\circ}\text{C}, -20 \sim -40 \, ^{\circ}\text{C}(-4 \sim -40 \, ^{\circ}\text{F}): \pm 2 \, ^{\circ}\text{C}, 200 \sim 300 \, ^{\circ}\text{C}(392 \sim 572 \, ^{\circ}\text{F})/-40 \sim -50 \, ^{\circ}\text{C}(-40 \, ^{\circ}\text{F} \sim -50 \, ^{\circ}\text{F}): \pm 2 \, ^{\circ}\text{C} \sim \pm 5 \, ^{\circ}\text{C}$
- 3 .Resolution:0.1C
- 4. Power supply:1.5V LR1130 batteries