

RHA-100

RHA

RHA Specifications

Specifications

Operating Temperature -84°F -32°F

Storage Temperature -60°F - 32°F

Weight 1.100-1.400sg

Accuracy

Temperature 5°F

Weight 5°F

Resolution 0.01sg

Resolution

Temperature ±5°F

Weight ±5°F

Resolution 0.01sg±