

## DM-01A measuring instruments

### Specification

1. in/mm: inch/metric conversion
2. RESET: origin resetting
3. TOL: tolerance setting
4. HOLD: data hold
5. R/A: relative/absolute measurement
6. conversion
  - +: positive setting
  - : negative setting
7. Larger LCD display

8. Type	Range	Resolution	Accuracy
DM-01	0-25mm/0-1"	0.001mm/0.00005"	0.002mm 0.001"