

Functional testing:(fitted with battery ,display:January1 ,2004, PM12:00 00oC temperature value)

1:TIME key,time setting,switch display time /date.Hold down the TIME button 2 seconds to enter time settings, and then

TIME button set the corresponding bit will be blinking ,set the following order:12/24 hours , seconds, hours , minutes ,year ,month , day,

2:UP button ,forward button.Press TIME button 2 seconds later, according to the objectives to be set up ,transfer press UP key to advance to the set position.

3:MAX/MIN button:Displays the maximum/ minimum temperature humidity recorder in the normal state, according to MAX/MIN key to switch showed the largest→minimum value of the current temperature and humidity.In the MAX or MIN displays status, no buttons automatically after 8 seconds to return the current temperature and humidity display.The maximum / minimum temperature recorded humidity removal,in the MAX or MIN of the state, hold down the MAX/MIN button 2 seconds clear of the show the highest / most low humidity, and return the current temperature and humidity display.

4:oC /oF key:Switch degrees Celsius / Fahrenheit.