




GM1361 湿度 温度 湿度温度 湿度温度 K

Diagram descriptions



- (1). LCD
- (2). ON/OFF button
- (3). Temperature switch and LED on/off button
- (4). Temperature maximum / minimum measuring button
- (5). Humidity maximum / minimum measuring button
- (6). Temperature data hold button
- (7). Humidity data hold button
- (8). Connection leadwire
- (9). Humidity & temperature sensor
- (10). K-type thermocouple



ABS

2.5

-10°C ~ 50°C -20°C ~ 50°C K

-1°C + 1°C -1.8°F + 1.8°F

-3% + 3% 30-95% ; -5% + 5% 10-30%

C / F

/

0.1°C

湿度0.1RH
温度2.5/℃
秒/分钟
K
LCD
4×1.5V AAA
秒


1 16.5×7.6×3.7
2 245
秒
1
2 4 AAA 1.5V
3 1 K
4 1 60 250
5 1
6 1