

## I2000 電子秤 Kitken



1. Power On / Off
2. 電源
3. Calibration
4. 設定
5. Tare Weight



- 500g
- 0.01g
- 0.01g
- 6g
- 180g
- 電池
- 2 \* AAA