

METER8



Radiation Detector

Sound Level Meter


Infrared Thermometer

Light Meter

Anemometer

GM1361 湿度温度计

Diagram descriptions



- (1). LCD
- (2). ON/OFF button
- (3). Temperature switch and LED on/off button
- (4). Temperature maximum / minimum measuring button
- (5). Humidity maximum / minimum measuring button
- (6). Temperature data hold button
- (7). Humidity data hold button
- (8). Connection leadwire
- (9). Humidity & temperature sensor
- (10). K-type thermocouple

HUMIDITY&TEMPERATURE METER

GM1361



Temperature Range:
-10°C~50°C (-20°C~50°C K-type)

Accuracy of temperature:
±1°C or ±1.8°F

Humidity Range: 5%RH~98%RH

Accuracy of humidity:
±3% (30-95%) ; ±5% (10-30%)



ABS

2.5

-10°C~50°C -20°C~50°C K

-1°C + 1°C -1.8°F + 1.8°F

-3% + 3% 30%~95% ; -5% + 5% 10-30%

C / F

0.1°C

0.1RH
2.5/0
K
4 X 1.5V AAA



16.5 X 7.6 X 3.7
245
1x1 Hygrothermograph
2x4xAAA 1.5V
3x1xK
4x1 60x250
5x1x
6x1x