

TBT-08H

Convenient

4 buttons

temperature. Please

temperature

temperature

temperature

temperature. Please



1.ON / OFF

2.C / F

3.Hold

4.MIN / MAX



1. 300°C - 50°C

2. Accuracy 0.1°C - 20°C - 100°C - 4°C - 212°F ± 1°C - 100°C - 200°C - 212°C - 392°F ± 2°C ± -20°C - 40°C - 4°C - 40°F ± 2°C - 200°C - 300°C - 392°C - 572°F ± - 40°C - 50°C - 40°F - 50°F ± 2°C ± 5°C ±

3. Resolution 0.1C

4. 1.5V LR1130