

Thermomter HT-5

Spec :

1. 1000 100 100
2. 1000 100
3. °C / °F 100 1000 100
4. Temperature range : -50 °C ~ + 110 °C (-58 °F ~ + 230 °F)
5. Sensing : 1M
6. Battery : AG13 1.5V * 1