

Portable USB Thermometer HT-161

Sepcifications:

Record 21000 temperature and humidity counts simultaneously.

LCD display for easily reading

USB connect to PC

Temp measurement range $-40^{\circ}\text{C}\sim 105^{\circ}\text{C}$ $-40^{\circ}\text{F}\sim 221^{\circ}\text{F}$

Temp measurement accuracy $\pm 1^{\circ}\text{C}$ $\pm 2^{\circ}\text{F}$

Temp display resolution 0.1°C 0.1°F

Humidity measurement range $0\% \text{ RH}\sim 100\% \text{ RH}$

Humidity measurement accuracy $\pm 3\% \text{ RH}$

Humidity display resolution $0.1\% \text{ RH}$