

Temperature or remove humidity , the maximum /minimum/temperature humidity records.

In the normal state, according to MAX/MIN key to switch showed the largest,minimum,value of the current temperature and humidity. In the MAX or MIN displays status, no buttons automatically after 8 seconds to return the current temperature and humidity display. The maximum/minimum temperature recorded humidity removal, in the MAX or MIN of the state , hold down the MAX/MIN button 2 seconds clear of the show the highest/ most low humidity, and return the current temperature and humidity display.

RESET button : clear reset.

Fix the unit on a wall or place on desktop.

Product use one (1.5V) AAA batteries. Font fuzzy, please replace the battery ,and

Pattention to environmental protection.

*C model with 1.5-meter temperature and humidity sensing line