

## DC103 Temperature & Humidity Meter

### Specification:

- Temperature Range:
  - Indoor □ -10°C □ +50°C (+14°F □ +122°F)
  - Outdoor □ -50°C □ +70°C (-58°F □ +158°F)
- Humidity Range: indoor 20% ~ 90% RH
- Power-supply: 1.5V (AG13) x 1

### Functions:

- \* Indoor/outdoor temperature & indoor humidity display
  - \* Temperature unit °C/°F changeable
  - \* Memorized MAX/MIN values of indoor/outdoor temperature and indoor humidity
  - \* Frost point alarm: -1°C □ +4°C (+30.2°F □ +39.2°F)
  - \* Display of comfort degree
    - appears @ indoor Temperature: 20°C □ 25°C □ 68°F □ 77°F □ & Indoor Humidity: 40%RH □ 70%RH
    - appears when Indoor Humidity: >70%RH.
    - appears when Indoor Humidity: <40% RH
- Nothing appears when indoor temperature >25°C (77°F ) OR < 20°C (68°F ) and the Humidity □ 40%RH ~70%RH.