

HT-6888

METERS



Features

1. Temperature -50~1300°C
2. Accuracy ±1.5% or ±1.5°C
3. Display = 50 digits
4. Memory
5. Auto power off
6. Auto hold
7. °C/°F switch
8. Resolution 0.10 to 1.0
9. MAX, MIN, DIF, AVG function
10. Large LCD display
11. Resolution 0.1°C (0.1°F)
12. Auto/Manual