Specification:

- 1. Measuring ranges:0.0-14.0pH
- 2. Accuracy:±0.01PH
- 3. Resolution: 0.01PH
- 4. Operating temperature : $0 \sim 80^{\circ}C$
- 5. Calibration: two points automatic calibration
- 6. Power supply:2*1.5v(keep using more than 500 hours)
- 7. Dimension: 153*29*16mm
- 8. Weight: 52g

Operation:

1.Remove the protective cap.

2. First rinse the electrode with distilled water , and dry it with filter pater.

- 3.Turn the meter on by pressing the ON/OFF key.
- 4. Immerse the ph meter electride in the solution to be tested .

5. Stir gently and wait for the reading to stablilize.

6.After finished ,clear the electrode with distilled water turn the meter off by pressing the "ON/OFF" key.

7. Always replace the protective cap after use .