

Temperature and Humidity Data Logger HT-160

Specifications and parameters

Temperature measurement range -40°C — 105°C / -40°F — 221°F

Temperature measurement accuracy $\pm 1^{\circ}\text{C}$ / $\pm 2^{\circ}\text{F}$

Temperature display resolution 0.1°C / 0.1°F

Humidity measurement range 0% RH— 100% RH

Humidity measurement accuracy $\pm 3\%$ RH

Humidity display resolution 0.1% RH

Using temperature -40°C — 105°C / -40°F — 221°F

Storage temperature -40°C — 125°C / -40°F — 257°F