



Ra Rz

Ra 0.05-10.00um/1.000-400.0uinch

Rz 0.020-100.0um/0.780-4000uinch

10

6

10um

16MN 1.6gf

90°

48

17.5mm/0.7inch

0.25 / 0.8 / 2.5

1 5

$0.25 Vt = 0.135$

$0.8 Vt = 0.5$

$2.5 Vt = 1$

$Vt = 1$

$0.001\mu m < 10\mu M$

$10\mu M = < 100\mu m$   $0.01\mu M$

$0.1\mu m IF = 100\mu m$

5

4 10

0 50°C

< 80



140x57x48

420