



**HTC-3** 温湿度计



**规格**

- 测量范围: -10°C ~ +50°C / -14°F ~ +122°F
- 精度: ±1°C / ±1.8°F
- 分辨率: ±0.1°C / ±0.2°F
- 湿度范围: 10% ~ 99% RH
- 湿度精度: ±5% RH
- 湿度分辨率: 1%
- 电源: AAA 1.5V

**功能**

- 温度/湿度
- °C/°F 温度单位切换
- °C/°F 湿度单位切换
- 12/24 小时制
- 背光显示
- 蜂鸣器报警
- 低功耗
- 大液晶显示

**注意**

1. First time use, please press the power button for 3 seconds to enter the factory default mode.
2. If you want to reset the device, please press the power button for 3 seconds.
3. Please do not use the device in the rain or in a very humid environment.



Escrow.com TT  
3



/



12