

KL-03 II A PH Meter

Features

0.00-14.00pH, ±0.1pH, 0.01pH, 0C-50C, BNC + 120X 26X 70mm, pH

Specs

0.00-14.00pH

±0.1pH

0.01pH

0C-50C

0C-50C

BNC + 120X 26X 70mm

120X 26X 70mm

70mm

pH

Use

1. Remove

2. First

ON 3. Turn

4. Immerse pH

5. Stir

6. After

OFF

7. Always

pH