

KL-03 II A PH Meter

Features

0.00 to 14.00 pH range, 0.1 pH resolution, 0.01 pH resolution, 0C- 50C temperature range, 0C- 50C temperature range, BNC + 1 input, 120 X 26 X 70 mm, 70 mm pH range

Specs

0.00-14.00pH

±0.1PH

0.01PH

0C- 50C

0C- 50C

BNC + 1

120 X 26 X 70

70

pH

Use

1.Remove

2.First

ON 3.Turn

4.Immerse pH

5.Stir

6.After

OFF

7.Always

pH