Features:

The brix and water content, and the baume are always importance to prove the honey's quality. Our honey refractometers are best tool to the farmer to test their honey.

Sepcifications:

Scale range:58-90%Brix

38-43Be'

10-33%water

Minimum scale: 1%Brix

0.5Be¹

1%water

Accuracy: ±1%

±0.5Be¹

±1%water

SIZE:Ø24.5X140mm,

Weight: 0.115KG