

Specifications

The temperature can be measured from -9 to +65°C.
1,5V one-off battery with a running time of about 2000 hours.

Instructions

1. Put the thermoeter around the bottle (of a diameter from 75 to 90 mm) and make sure that the contact
2. switch and the metallic sensor touch the bottle. After about 2 seconds you will see the temperature on the screen.